






Build instructions by Dorian Bricktron
dorianbricktron.com



**EXTRA
PARTS**



1x



1x






CAUTION

**SPECIFIC DESIGN
NOT AS STURDY AS A REGULAR SET**


**MIGHT INCLUDE "ILLEGAL BUILDING
TECHNIQUES" & WEAK CONNECTIONS**

**BENDING OF THE MATERIALS CAN CAUSE
PERMANENT DAMAGE**




1





2






3







5




1







2









3










6












2x
54200, 11

2x
4599b, 11

2x
3623, 11

4x
11209, 11

1x
35654, 11



1x
65202, 11

2x
85861, 85

2x
15712, 85

2x
2412b, 85

1x
50943, 85

2x
30414, 85

3x
3710, 86

2x
85861, 1

2x
2412b, 1

2x
85984, 1

4x
11477, 1

2x
30413, 1

1x
45677, 1

1x
3002, 5

1x
3020, 4

1x
3004, 69

1x
2432, 3

1x
3829c01, 3

2x
3710, 103

1x
3020, 6

2x
3070b, 7

2x
54200, 7

2x
15573, 7

2x
3023, 7

2x
11477, 7

1x
15068, 7


6x
63864, 7

2x
3021, 7


2x
BRICKTRON

4x
50745, 7

3x
3666, 7



2x
22889, 7




2x
87609, 7

2x
3069b, 12

2x
4073, 17

2x
4073, 19



2x
57783, 15

2x
98138, 14

1x
2431, 14

4x
11208, 95

